CERTIFICATE OF APPROPRIATENESS

Application Date: February 12, 2024

ļ

Applicant: Israel Valles, agent for Robert W. Drummond, owner

- Property:721 Columbia Street, Lot 7, Block 257, Houston Heights Neighborhood
Subdivision. The property includes a historic 2,589 square foot, one-story wood
single-family residence and attached carport situated on a 6,600 square foot (132'
x 50') interior lot.
- **Significance:** Contributing Craftsman Bungalow style residence, constructed circa 1920, located in the Houston Heights South Historic District.
 - **Proposal:** Alteration Addition, windows, porch

Rear Addition:

- A partial second story addition (660 square feet) at the rear of the existing one-story single-family dwelling with smooth Hardie plank siding.
- A partial demolition will remove a non-historic side addition and carport on the south elevation.
 - **this work was completed in February, 2024 at the time of the initial application process.
- All windows included in the addition will be one-over-one inset and recessed wood windows.
- A small, uncovered side deck will be added to the south (left) elevation at the rear 50% of first floor, as well as a small rear (west) porch.

Windows:

Existing windows on the east (front), north (right), and south (left) elevations are non-historic and will be replaced with various sets of oneover-one wood windows. Photographic evidence from the interior shows ghosting and infill of previous window openings.

Front Porch:

- Replace non-historic metal columns and railings with tapered wood columns and wood railings to match the context area.
- Replace existing porch tile flooring with wood decking.

Information subject to change before final staff report

Recommendation: Denial of COA, Issuance of COR for work completed on removal of attached carport and non-historic rear side addition.

Approval of proposed partial rear addition, windows, and front porch as is.

HAHC Action: -

APPROVAL CRITERIA

ALTERATIONS, REHABILITATIONS, RESTORATIONS AND ADDITIONS

Sec. 33-241: HAHC shall issue a certificate of appropriateness for the alteration, rehabilitation, restoration or addition of an exterior feature of (i) any landmark, (ii) protected landmark, (iii) any building, structure or object that is part of an archaeological site, or (iv) contributing building in a historic district upon finding that the application satisfies the following criteria, as applicable:

S	D	NA		S - satisfies D - does not satisfy NA - not applicable
\boxtimes			(1)	The proposed activity must retain and preserve the historical character of the property;
\boxtimes			(2)	The proposed activity must contribute to the continued availability of the property for a contemporary use;
			(3)	The proposed activity must recognize the building, structure, object or site as a product of its own time and avoid alterations that seek to create an earlier or later appearance;
\boxtimes			(4)	The proposed activity must preserve the distinguishing qualities or character of the building, structure, object or site and its environment;
\boxtimes			(5)	The proposed activity must maintain or replicate distinctive stylistic exterior features or examples of skilled craftsmanship that characterize the building, structure, object or site;
\bowtie			(6)	New materials to be used for any exterior feature excluding what is visible from public alleys must be visually compatible with, but not necessarily the same as, the materials being replaced in form, design, texture, dimension and scale;
			(7)	The proposed replacement of exterior features, if any, should be based on an accurate duplication of features, substantiated by available historical, physical or pictorial evidence, where that evidence is available, rather than on conjectural designs or the availability of different architectural elements from other structures;
\boxtimes			(8)	Proposed additions or alterations must be done in a manner that, if removed in the future, would leave unimpaired the essential form and integrity of the building, structure, object or site;
			(9)	The proposed design for any exterior alterations or addition must not destroy significant historical, architectural, archaeological or cultural material, including but not limited to siding, windows, doors and porch elements;
\boxtimes			(10)	The proposed alteration or addition must be compatible with the massing, size, scale material and character of the property and the context area; and
			(11)	The distance from the property line to the front and side walls, porches, and exterior features of any proposed addition or alteration must be compatible with the distance to the property line of similar elements of existing contributing structures in the context area.

HEIGHTS DESIGN GUIDELINES MEASURABLE STANDARDS

S D NA <u>S - satisfies</u> <u>D - does not satisfy</u> <u>NA - not applicable</u>

 \square \square

Maximum Lot Coverage (Addition and New Construction)

LOT SIZE MAXIMUM LOT COVERAGE

<4000	.44 (44%)
4000-4999	.44 (44%)
5000-5999	.42 (42%)
6000-6999	.40 (40%)
7000-7999	.38 (38%)
8000+	.38 (38%)

Existing Lot Size: 6,600 Max. Allowed: 2,640 Proposed Lot Coverage: 2,050 Remaining Amount: 590

 \boxtimes \Box \Box

Maximum Floor Area Ratio (Addition and New Construction)

LOT SIZE	MAXIMUM FAR
<4000	.48
4000-4999	.48
5000-5999	.46
6000-6999	.44
7000-7999	.42
8000+	.40


Existing Lot Size: 6,600 Max. FAR Allowed: 2,904 Proposed FAR: 2,740 Remaining Amount: 164

 \boxtimes \Box \Box


Side Wall Length and Insets (Addition and New Construction)

MEASUREMENT	APPLICATION
50 FT.	Maximum side wall length without inset (1-story)
40 FT.	Maximum side wall length without inset (2-story)
1 FT.	Minimum depth of inset section of side wall (1-story)
2 FT.	Minimum depth of inset section of side wall (2-story)
6 FT.	Minimum length of inset section of side wall

Side Wall Length: 36'- 9" Inset Length: 6' Inset on North side: 2' Inset on South side: 2'



\boxtimes \square \square	Rear Setbacks (Addition and New Construction)				
		equires a minimum setback of three feet from the rear property line for all nder the following circumstances:				
	 A front-facing (garage which is located with its rear wall at the alley may have a zero-foot setback.				
	 An alley-loading garage generally must be located to establish a minimum of 20 feet of clearance from an opposing alley-loading garage door, the rear wall of a front-facing garage, or a fence; a 24-foot clearance is preferred. 					
	Proposed rear s	etback: 28'				
\boxtimes \Box \Box	Porch Eave Heig	ght (Addition and New Construction)				
	MEASUREMENT	APPLICATION				
	9-11 FT.	Minimum and maximum 1-story porch eave height.				
	Proposed porch	eave height: 10' – 6"				
	Building Wall (P	late) Height (Addition and New Construction)				
	MEASUREMENT	APPLICATION				
	36 IN.	Maximum finished floor height (as measured at the front of the structure)				
	10 FT.	Maximum first floor plate height				
	9 FT.	Maximum second floor plate height				
		ed floor: 1' – 6" or plate height: 10' – 6" od floor plate height: 9' – 0"				



PROPERTY LOCATION IN HISTORIC DISTRICT

INVENTORY PHOTO

EAST (FRONT) ELEVATION




CURRENT PHOTO EAST (FRONT) ELEVATION



HISTORIC DOCUMENTATION

SANBORN 1924-1950_SHEET 722



BLA – DATE UNKNOWN

a second	11 1 - 11.	IMPROVEMENTS	
Map No Addition	Houston HE	No. Sq. 1/21 Price Per Sq. Ft.	0 -7 0
Block 257		Ft_//34 / \$ Percent Good	410
OWNER Willie	Jos. 7.	15 5 65	1470
ADDRESS	and the second second	Other Bldgs.	
BASEMENT, Whole Part	FLOORING, Pine, Hardwood, Cement, Tile, Marble, Dirt	32 11 1	50
FOUNDATIÓN, Concrete, Stone, Brick, Piers, Posts. WALLS, Brick_Stone Hollow Tile, Stucco, Metal, Concrete Blogeks, Box Weatherbhard_ ROOF CONS., Concrete, Steel, Wood Truss ROOF, Hip, Gable, Mansard,	INTERIOR TRIM, Plaster, Hardwood, Marble, Metal, Built-in Features HEATING, Furnace, Stoves, Fireplace, Chimneys, Gas LIGHTING, Electricity	Total All Bidgs.	1520
Flat	PLUMBING, Sewer, Water,	LAND VALUE	
ROOFING, Composition, Metal, Slate, Wood, Shin- gles, Tile, Asbestos	_Baths	Unit Front Ft. Front x Depth Value Factor Value \$ 50x132(29) 9 13 10	510
EXTERIOR TRIM, Stone, Terra Cotta, Metal, Wood, Marble, Granite	CONDITION, Good, Fair, Bad, Obsolete		
PERMIT DATE N	0AMT	TOTAL	
		10-000	

1969 BLA



1976 BLA

GITY OF INCLUSION ILLAS	: 050.004-00.006/7
ACN MARRIS COUNTY BUILDING ASSESSMENT	CAR_ UP + 105.
ADDRESS	360 19 min 175.
GARAS AND CONTRACT	20 11111 77
the provence NO. VOL. PG. THE ITEM	15 17 18 18 18 18 18 18 18 18 18 18 18 18 18
MOROVEMENTS 1980 20 233 01	The second se
AV9	
No. StorlesFOUNDATION ROOF TYPE GARAGE	33 12
DepiexBeam & PiersHippedRoof	33 11
Corr. Apt Correr. Diks Flat Floor Revalued	30
BesamentFLOORING RODFING Doore	100/10
Dirth Madwood Come Share 1978 7100 To Ta Carve 3410	CLASS W. R.W.
Stone V Terrazzo, Tar & Gravel CARPORT NEW OWNER	CLASSY: BuiltDepr Bess Uning \$A/C&C/H@ \$Total Uning 8
Adhustos Vinys Roof	Dr. 1. 605 Tu. + 5 To 55
ShilesWieW CatsNITEMON FASH Ploor	In 1100 200 1000 01/11/2 110- 1100
HEATING & COOLING Sheetrock	0.1. 145. 1.10 160. 100 110 770 A
No. Bethe Plaster Plaster	CAR- 360. 100 360 21,101.1
No. Pplacos	1015 4 Do Ary - 295 D.
Parmit Va 050-004-00-006-7 1977 01/24/77 I 4260 250.00 10650 532	1970.
mor. 6 more di nenve di	
and DECT 4 197	
ON NAME VALUE HON	
ARIAN FALVERSE	Appraiser's name & date Total 100% Value & 12/20
I FOS MARTA	Appendistria mart & data 2000 10 10/10 1. Por 10 1 Hactor X3.5
the second se	M. Dechina managen 69 was 1 N new 100% - 10650
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	CD 32%-3410
and the second	



CONTEXT AREA – COLUMBIA STREET









5/2/2024

EXISTING PHOTOS

EAST (FRONT) ELEVATION



EAST AND SOUTH ELEVATION WITH ATTACHED CARPORT

Carport and non-historic side addition has since been removed.



SOUTH (LEFT) ELEVATION - CARPORT SIDE



CAMERA FACING WEST - CARPORT ATTACHED TO SOUTH ELEVATION



Carport and non-historic side addition has since been removed.



SOUTH ELEVATION OF SIDE WALL NOT COVERED BY CARPORT


WEST (REAR) ELEVATION



OBLIQUE VIEW OF WEST (REAR) ELEVATION



NORTH (RIGHT) ELEVATION



INTERIOR WINDOW INFILL/GHOSTING OF ORIGINAL WINDOW OPENINGS:


EAST (FRONT) ELEVATION




EAST (FRONT) ELEVATION



NORTH (RIGHT) ELEVATION



NORTH (RIGHT) ELEVATION




5/2/2024


1ST & 2ND RED TAG NOTICE - INSPECTOR PHOTOS AFTER CARPORT REMOVAL




1ST & 2ND RED TAG NOTICE - INSPECTOR PHOTOS AFTER CARPORT REMOVAL





SITE PLAN








5/2/2024














WINDOW SCHEDULE



CERTIFICATE OF APPROPRIATENESS

WINDOW WORKSHEET

EXISTING WINDOW SCHEDULE									
Window Material Lite		Style	Dimensions Recessed/Inset		Original/	Existing to			
		Pattern				Replacement	Remain		
Ex. A1	Wood	1/1	DH	32 x 66	Recessed	Original	No		
A1	VYNIL	6/6	SH		INSET	REPLACEMENT	NO		
A2	VYNIL	6/6	SH		INSET	REPLACEMENT	NO		
B1	VYNIL	5/5	SH		INSET	REPLACEMENT	NO		
B2	VYNIL	5/5	SH		INSET	REPLACEMENT	NO		
B3	VYNIL	5/5	SH		INSET	REPLACEMENT	NO		
B4	VYNIL	5/5	SH		INSET	REPLACEMENT	NO		
C1	VYNIL	1/1			INSET	REPLACEMENT	NO		
D1	VYNIL	2/2			INSET	REPLACEMENT	NO		
D2	VYNIL	2/2			INSET	REPLACEMENT	NO		

DAMAGE TO EXISTING WINDOWS							
Window Describe Damage							
Ex. A1	Glass is broke, window is inoperable, rail is rotten, and frame is broken						

PROPOSED WINDOW SCHEDULE									
Window	Material	Lite Pattern	Style	Dimensions	Recessed/ Inset	Brand/ Vendor	Other		
Ex. A1	Wood	1/1	DH	32 х бб	Recessed	Plygem			
A1	WOOD	1/1	DH	36x72	RECESSED				
A2	WOOD	1/1	DH	36x72	RECESSED				
A3	WOOD	1/1	DH	36x72	RECESSED				
A4	WOOD	1/1	DH	36x72	RECESSED				
A5	WOOD	1/1	DH	36x72	RECESSED				
A6	WOOD	1/1	DH	36x72	RECESSED				
A7	WOOD	1/1	DH	36x72	RECESSED				
A8	WOOD	1/1	DH	36x72	RECESSED				
A9	WOOD	1/1	DH	36x72	RECESSED				

Must include photos of all windows with labels indicated on this sheet

Must include manufacture's specifications and details for all proposed windows

*** Use additional sheets as necessary