



**HOUSTON FIRE DEPARTMENT
PUBLIC AFFAIRS OFFICE
NEWS RELEASE**

FOR IMMEDIATE RELEASE

October 27, 2009

CONTACT: HFD Public Affairs, 713-495-7906

INCIDENT UPDATE: 10700 SABO RD

Houston Fire Department arson investigators have determined the cause of a fire this morning on Sabo Road in southeast Houston accidental fire due to an electrical malfunction in a multi-outlet power strip.

HFD was dispatched to a fire at the Sabo Village Apartments in the 10700 block of Sabo just before 5:30 a.m. this morning, October 27, 2009. The 2-alarm fire was taped-out at about 6:30 a.m. Four apartment units on the second floor had moderate to heavy fire damage; four units on the first floor had water damage and an additional four - eight units suffered light smoke damage from the fire.

-30-

Working Smoke Detectors Save Lives!

