

**Land Assemblage Redevelopment Authority RFP
Attachment L
Lot Inspections**

Area	HCAD	COH Tract #:	Survey Date:
Fifth Ward	0121620000004	5533	May 17, 2006

Address No.	Prefix	Street Name	St. Type	Suffix
3115		BRILL		

Curb Cut

Lot A (left) Existing Curb Cut No existing curb cut

Lot B (If applicable-right) Existing curb cut No existing curb cut
 Parcel is only one lot

Lot C (If applicable-furthest right) Existing curb cut No existing curb cut
 Parcel is only one lot

Street Edge (Prevailing on Street) Sidewalks Ditch and Culverts

Trees Located in Right-of-Way No trees observed in ROW Less than 3 trees
 Greater than 3 trees

Trees (>8" Caliper located on Site) No trees Less than 3 trees
 Greater than 3 trees

Existing Slab or Paving Removal Existing slab/pavement <10'-0" x 10'-0"
 Existing slab/pavement >10'-0" x 10'-0" Existing pier and beam

Existing Building Removal Existing structure <10'-0" x 10'-0"
 Existing structure >10'-0" x 10'-0" Existing pier and beam

Septic Tanks Septic tanks visually identified No visual evidence of septic tank

Wells Well visually identified No visual evidence of well

Vegetation, Trash or Debris Removal Planting and debris <10 cubic yards
 Planting and debris > 10 cubic yards

Existing Fences on Site Chain Link Fence Wood Fence
 Wrought Iron/Metal Fence

Power Poles - Front of Lot/Back of Lot Power pole located at front of lot
 Power pole located in ROW at back of lot No power pole visible on lot

Drainage Lot visibly slopes from back to front
 Lot visibly slopes from front to back Can't tell/Unable to visually determine slope

**Land Assemblage Redevelopment Authority RFP
Attachment L
Lot Inspections**

Area	HCAD	COH Tract #:	Survey Date:
Fifth Ward	0121620000005	2557	May 17, 2006

Address No.	Prefix	Street Name	St. Type	Suffix
3119		BRILL		

Curb Cut

Lot A (left) Existing Curb Cut No existing curb cut

Lot B (If applicable-right) Existing curb cut No existing curb cut
 Parcel is only one lot

Lot C (If applicable-furthest right) Existing curb cut No existing curb cut
 Parcel is only one lot

Street Edge (Prevailing on Street) Sidewalks Ditch and Culverts

Trees Located in Right-of-Way No trees observed in ROW Less than 3 trees
 Greater than 3 trees

Trees (>8" Caliper located on Site) No trees Less than 3 trees
 Greater than 3 trees

Existing Slab or Paving Removal Existing slab/pavement <10'-0" x 10'-0"
 Existing slab/pavement >10'-0" x 10'-0" Existing pier and beam

Existing Building Removal Existing structure <10'-0" x 10'-0"
 Existing structure >10'-0" x 10'-0" Existing pier and beam

Septic Tanks Septic tanks visually identified No visual evidence of septic tank

Wells Well visually identified No visual evidence of well

Vegetation, Trash or Debris Removal Planting and debris <10 cubic yards
 Planting and debris > 10 cubic yards

Existing Fences on Site Chain Link Fence Wood Fence
 Wrought Iron/Metal Fence

Power Poles - Front of Lot/Back of Lot Power pole located at front of lot
 Power pole located in ROW at back of lot No power pole visible on lot

Drainage Lot visibly slopes from back to front
 Lot visibly slopes from front to back Can't tell/Unable to visually determine slope

**Land Assemblage Redevelopment Authority RFP
Attachment L
Lot Inspections**

Area	HCAD	COH Tract #:	Survey Date:
Fifth Ward	0260370000005	2588	May 17, 2006

Address No.	Prefix	Street Name	St. Type	Suffix
3014		CACTUS		

Curb Cut				
Lot A (left) <input type="checkbox"/> Existing Curb Cut <input type="checkbox"/> No existing curb cut				
Lot B (If applicable-right) <input type="checkbox"/> Existing curb cut <input type="checkbox"/> No existing curb cut <input type="checkbox"/> Parcel is only one lot				
Lot C (If applicable-furthest right) <input type="checkbox"/> Existing curb cut <input type="checkbox"/> No existing curb cut <input type="checkbox"/> Parcel is only one lot				
Street Edge (Prevailing on Street) <input type="checkbox"/> Sidewalks <input type="checkbox"/> Ditch and Culverts				
Trees Located in Right-of-Way <input type="checkbox"/> No trees observed in ROW <input type="checkbox"/> Less than 3 trees <input type="checkbox"/> Greater than 3 trees				
Trees (>8" Caliper located on Site) <input type="checkbox"/> No trees <input type="checkbox"/> Less than 3 trees <input checked="" type="checkbox"/> Greater than 3 trees				
Existing Slab or Paving Removal <input type="checkbox"/> Existing slab/pavement <10'-0" x 10'-0" <input type="checkbox"/> Existing slab/pavement >10'-0" x 10'-0" <input type="checkbox"/> Existing pier and beam				
Existing Building Removal <input type="checkbox"/> Existing structure <10'-0" x 10'-0" <input type="checkbox"/> Existing structure >10'-0" x 10'-0" <input type="checkbox"/> Existing pier and beam				
Septic Tanks <input type="checkbox"/> Septic tanks visually identified <input checked="" type="checkbox"/> No visual evidence of septic tank				
Wells <input type="checkbox"/> Well visually identified <input checked="" type="checkbox"/> No visual evidence of well				
Vegetation, Trash or Debris Removal <input checked="" type="checkbox"/> Planting and debris <10 cubic yards <input type="checkbox"/> Planting and debris > 10 cubic yards				
Existing Fences on Site <input checked="" type="checkbox"/> Chain Link Fence <input type="checkbox"/> Wood Fence <input type="checkbox"/> Wrought Iron/Metal Fence				
Power Poles - Front of Lot/Back of Lot <input checked="" type="checkbox"/> Power pole located at front of lot <input type="checkbox"/> Power pole located in ROW at back of lot <input type="checkbox"/> No power pole visible on lot				
Drainage <input type="checkbox"/> Lot visibly slopes from back to front <input type="checkbox"/> Lot visibly slopes from front to back <input checked="" type="checkbox"/> Can't tell/Unable to visually determine slope				

**Land Assemblage Redevelopment Authority RFP
Attachment L
Lot Inspections**

Area	HCAD	COH Tract #:	Survey Date:
Fifth Ward	0092480000004	5522	May 18, 2006

Address No.	Prefix	Street Name	St. Type	Suffix
5707		COLFAX	ST	

Curb Cut

Lot A (left) Existing Curb Cut No existing curb cut

Lot B (If applicable-right) Existing curb cut No existing curb cut
 Parcel is only one lot

Lot C (If applicable-furthest right) Existing curb cut No existing curb cut
 Parcel is only one lot

Street Edge (Prevailing on Street) Sidewalks Ditch and Culverts

Trees Located in Right-of-Way No trees observed in ROW Less than 3 trees
 Greater than 3 trees

Trees (>8" Caliper located on Site) No trees Less than 3 trees
 Greater than 3 trees

Existing Slab or Paving Removal Existing slab/pavement <10'-0" x 10'-0"
 Existing slab/pavement >10'-0" x 10'-0" Existing pier and beam

Existing Building Removal Existing structure <10'-0" x 10'-0"
 Existing structure >10'-0" x 10'-0" Existing pier and beam

Septic Tanks Septic tanks visually identified No visual evidence of septic tank

Wells Well visually identified No visual evidence of well

Vegetation, Trash or Debris Removal Planting and debris <10 cubic yards
 Planting and debris > 10 cubic yards

Existing Fences on Site Chain Link Fence Wood Fence
 Wrought Iron/Metal Fence

Power Poles - Front of Lot/Back of Lot Power pole located at front of lot
 Power pole located in ROW at back of lot No power pole visible on lot

Drainage Lot visibly slopes from back to front
 Lot visibly slopes from front to back Can't tell/Unable to visually determine slope

**Land Assemblage Redevelopment Authority RFP
Attachment L
Lot Inspections**

Area	HCAD	COH Tract #:	Survey Date:
Fifth Ward	0561330000009	2578	May 17, 2006

Address No.	Prefix	Street Name	St. Type	Suffix
4006		EDDIE		

Curb Cut

Lot A (left) Existing Curb Cut No existing curb cut

Lot B (If applicable-right) Existing curb cut No existing curb cut
 Parcel is only one lot

Lot C (If applicable-furthest right) Existing curb cut No existing curb cut
 Parcel is only one lot

Street Edge (Prevailing on Street) Sidewalks Ditch and Culverts

Trees Located in Right-of-Way No trees observed in ROW Less than 3 trees
 Greater than 3 trees

Trees (>8" Caliper located on Site) No trees Less than 3 trees
 Greater than 3 trees

Existing Slab or Paving Removal Existing slab/pavement <10'-0" x 10'-0"
 Existing slab/pavement >10'-0" x 10'-0" Existing pier and beam

Existing Building Removal Existing structure <10'-0" x 10'-0"
 Existing structure >10'-0" x 10'-0" Existing pier and beam

Septic Tanks Septic tanks visually identified No visual evidence of septic tank

Wells Well visually identified No visual evidence of well

Vegetation, Trash or Debris Removal Planting and debris <10 cubic yards
 Planting and debris > 10 cubic yards

Existing Fences on Site Chain Link Fence Wood Fence
 Wrought Iron/Metal Fence

Power Poles - Front of Lot/Back of Lot Power pole located at front of lot
 Power pole located in ROW at back of lot No power pole visible on lot

Drainage Lot visibly slopes from back to front
 Lot visibly slopes from front to back Can't tell/Unable to visually determine slope

**Land Assemblage Redevelopment Authority RFP
Attachment L
Lot Inspections**

Area	HCAD	COH Tract #:	Survey Date:
Fifth Ward	0561330000006	2577	May 17, 2006

Address No.	Prefix	Street Name	St. Type	Suffix
4018		EDDIE		

Curb Cut

Lot A (left) Existing Curb Cut No existing curb cut

Lot B (If applicable-right) Existing curb cut No existing curb cut
 Parcel is only one lot

Lot C (If applicable-furthest right) Existing curb cut No existing curb cut
 Parcel is only one lot

Street Edge (Prevailing on Street) Sidewalks Ditch and Culverts

Trees Located in Right-of-Way No trees observed in ROW Less than 3 trees
 Greater than 3 trees

Trees (>8" Caliper located on Site) No trees Less than 3 trees
 Greater than 3 trees

Existing Slab or Paving Removal Existing slab/pavement <10'-0" x 10'-0"
 Existing slab/pavement >10'-0" x 10'-0" Existing pier and beam

Existing Building Removal Existing structure <10'-0" x 10'-0"
 Existing structure >10'-0" x 10'-0" Existing pier and beam

Septic Tanks Septic tanks visually identified No visual evidence of septic tank

Wells Well visually identified No visual evidence of well

Vegetation, Trash or Debris Removal Planting and debris <10 cubic yards
 Planting and debris > 10 cubic yards

Existing Fences on Site Chain Link Fence Wood Fence
 Wrought Iron/Metal Fence

Power Poles - Front of Lot/Back of Lot Power pole located at front of lot
 Power pole located in ROW at back of lot No power pole visible on lot

Drainage Lot visibly slopes from back to front
 Lot visibly slopes from front to back Can't tell/Unable to visually determine slope

**Land Assemblage Redevelopment Authority RFP
Attachment L
Lot Inspections**

Area	HCAD	COH Tract #:	Survey Date:
Fifth Ward	0040350000009	2587	May 17, 2006

Address No.	Prefix	Street Name	St. Type	Suffix
4501		EVELLA		

Curb Cut
Lot A (left) Existing Curb Cut No existing curb cut
Lot B (If applicable-right) Existing curb cut No existing curb cut
 Parcel is only one lot
Lot C (If applicable-furthest right) Existing curb cut No existing curb cut
 Parcel is only one lot

Street Edge (Prevailing on Street) Sidewalks Ditch and Culverts

Trees Located in Right-of-Way No trees observed in ROW Less than 3 trees
 Greater than 3 trees

Trees (>8" Caliper located on Site) No trees Less than 3 trees
 Greater than 3 trees

Existing Slab or Paving Removal Existing slab/pavement <10'-0" x 10'-0"
 Existing slab/pavement >10'-0" x 10'-0" Existing pier and beam

Existing Building Removal Existing structure <10'-0" x 10'-0"
 Existing structure >10'-0" x 10'-0" Existing pier and beam

Septic Tanks Septic tanks visually identified No visual evidence of septic tank

Wells Well visually identified No visual evidence of well

Vegetation, Trash or Debris Removal Planting and debris <10 cubic yards
 Planting and debris > 10 cubic yards

Existing Fences on Site Chain Link Fence Wood Fence
 Wrought Iron/Metal Fence

Power Poles - Front of Lot/Back of Lot Power pole located at front of lot
 Power pole located in ROW at back of lot No power pole visible on lot

Drainage Lot visibly slopes from back to front
 Lot visibly slopes from front to back Can't tell/Unable to visually determine slope

**Land Assemblage Redevelopment Authority RFP
Attachment L
Lot Inspections**

Area	HCAD	COH Tract #:	Survey Date:
Fifth Ward	0211390000032	5532	May 17, 2006

Address No.	Prefix	Street Name	St. Type	Suffix
3207		FARMER		

Curb Cut
Lot A (left) Existing Curb Cut No existing curb cut
Lot B (If applicable-right) Existing curb cut No existing curb cut
 Parcel is only one lot
Lot C (If applicable-furthest right) Existing curb cut No existing curb cut
 Parcel is only one lot

Street Edge (Prevailing on Street) Sidewalks Ditch and Culverts

Trees Located in Right-of-Way No trees observed in ROW Less than 3 trees
 Greater than 3 trees

Trees (>8" Caliper located on Site) No trees Less than 3 trees
 Greater than 3 trees

Existing Slab or Paving Removal Existing slab/pavement <10'-0" x 10'-0"
 Existing slab/pavement >10'-0" x 10'-0" Existing pier and beam

Existing Building Removal Existing structure <10'-0" x 10'-0"
 Existing structure >10'-0" x 10'-0" Existing pier and beam

Septic Tanks Septic tanks visually identified No visual evidence of septic tank

Wells Well visually identified No visual evidence of well

Vegetation, Trash or Debris Removal Planting and debris <10 cubic yards
 Planting and debris > 10 cubic yards

Existing Fences on Site Chain Link Fence Wood Fence
 Wrought Iron/Metal Fence

Power Poles - Front of Lot/Back of Lot Power pole located at front of lot
 Power pole located in ROW at back of lot No power pole visible on lot

Drainage Lot visibly slopes from back to front
 Lot visibly slopes from front to back Can't tell/Unable to visually determine slope

**Land Assemblage Redevelopment Authority RFP
Attachment L
Lot Inspections**

Area	HCAD	COH Tract #:	Survey Date:
Fifth Ward	0211440060003	5535	May 18, 2006

Address No.	Prefix	Street Name	St. Type	Suffix
3313		FARMER		

Curb Cut				
Lot A (left) <input type="checkbox"/> Existing Curb Cut <input checked="" type="checkbox"/> No existing curb cut				
Lot B (If applicable-right) <input type="checkbox"/> Existing curb cut <input type="checkbox"/> No existing curb cut <input type="checkbox"/> Parcel is only one lot				
Lot C (If applicable-furthest right) <input type="checkbox"/> Existing curb cut <input type="checkbox"/> No existing curb cut <input type="checkbox"/> Parcel is only one lot				
Street Edge (Prevailing on Street) <input checked="" type="checkbox"/> Sidewalks <input type="checkbox"/> Ditch and Culverts				
Trees Located in Right-of-Way <input type="checkbox"/> No trees observed in ROW <input type="checkbox"/> Less than 3 trees <input type="checkbox"/> Greater than 3 trees				
Trees (>8" Caliper located on Site) <input type="checkbox"/> No trees <input type="checkbox"/> Less than 3 trees <input checked="" type="checkbox"/> Greater than 3 trees				
Existing Slab or Paving Removal <input type="checkbox"/> Existing slab/pavement <10'-0" x 10'-0" <input type="checkbox"/> Existing slab/pavement >10'-0" x 10'-0" <input type="checkbox"/> Existing pier and beam				
Existing Building Removal <input type="checkbox"/> Existing structure <10'-0" x 10'-0" <input type="checkbox"/> Existing structure >10'-0" x 10'-0" <input type="checkbox"/> Existing pier and beam				
Septic Tanks <input type="checkbox"/> Septic tanks visually identified <input checked="" type="checkbox"/> No visual evidence of septic tank				
Wells <input type="checkbox"/> Well visually identified <input checked="" type="checkbox"/> No visual evidence of well				
Vegetation, Trash or Debris Removal <input checked="" type="checkbox"/> Planting and debris <10 cubic yards <input type="checkbox"/> Planting and debris > 10 cubic yards				
Existing Fences on Site <input checked="" type="checkbox"/> Chain Link Fence <input type="checkbox"/> Wood Fence <input type="checkbox"/> Wrought Iron/Metal Fence				
Power Poles - Front of Lot/Back of Lot <input checked="" type="checkbox"/> Power pole located at front of lot <input type="checkbox"/> Power pole located in ROW at back of lot <input type="checkbox"/> No power pole visible on lot				
Drainage <input checked="" type="checkbox"/> Lot visibly slopes from back to front <input type="checkbox"/> Lot visibly slopes from front to back <input type="checkbox"/> Can't tell/Unable to visually determine slope				

**Land Assemblage Redevelopment Authority RFP
Attachment L
Lot Inspections**

Area	HCAD	COH Tract #:	Survey Date:
Fifth Ward	0701040010016	5534	May 18, 2006

Address No.	Prefix	Street Name	St. Type	Suffix
0		JEWEL		

Curb Cut

Lot A (left) Existing Curb Cut No existing curb cut

Lot B (If applicable-right) Existing curb cut No existing curb cut
 Parcel is only one lot

Lot C (If applicable-furthest right) Existing curb cut No existing curb cut
 Parcel is only one lot

Street Edge (Prevailing on Street) Sidewalks Ditch and Culverts

Trees Located in Right-of-Way No trees observed in ROW Less than 3 trees
 Greater than 3 trees

Trees (>8" Caliper located on Site) No trees Less than 3 trees
 Greater than 3 trees

Existing Slab or Paving Removal Existing slab/pavement <10'-0" x 10'-0"
 Existing slab/pavement >10'-0" x 10'-0" Existing pier and beam

Existing Building Removal Existing structure <10'-0" x 10'-0"
 Existing structure >10'-0" x 10'-0" Existing pier and beam

Septic Tanks Septic tanks visually identified No visual evidence of septic tank

Wells Well visually identified No visual evidence of well

Vegetation, Trash or Debris Removal Planting and debris <10 cubic yards
 Planting and debris > 10 cubic yards

Existing Fences on Site Chain Link Fence Wood Fence
 Wrought Iron/Metal Fence

Power Poles - Front of Lot/Back of Lot Power pole located at front of lot
 Power pole located in ROW at back of lot No power pole visible on lot

Drainage Lot visibly slopes from back to front
 Lot visibly slopes from front to back Can't tell/Unable to visually determine slope

**Land Assemblage Redevelopment Authority RFP
Attachment L
Lot Inspections**

Area	HCAD	COH Tract #:	Survey Date:
Fifth Ward	0503460000065	2663	May 17, 2006

Address No.	Prefix	Street Name	St. Type	Suffix
0		KIRK		

Curb Cut	
Lot A (left)	<input checked="" type="checkbox"/> Existing Curb Cut <input type="checkbox"/> No existing curb cut
Lot B (If applicable-right)	<input type="checkbox"/> Existing curb cut <input type="checkbox"/> No existing curb cut <input type="checkbox"/> Parcel is only one lot
Lot C (If applicable-furthest right)	<input type="checkbox"/> Existing curb cut <input type="checkbox"/> No existing curb cut <input type="checkbox"/> Parcel is only one lot
Street Edge (Prevailing on Street) <input type="checkbox"/> Sidewalks <input checked="" type="checkbox"/> Ditch and Culverts	
Trees Located in Right-of-Way <input type="checkbox"/> No trees observed in ROW <input type="checkbox"/> Less than 3 trees <input type="checkbox"/> Greater than 3 trees	
Trees (>8" Caliper located on Site) <input type="checkbox"/> No trees <input type="checkbox"/> Less than 3 trees <input checked="" type="checkbox"/> Greater than 3 trees	
Existing Slab or Paving Removal <input type="checkbox"/> Existing slab/pavement <10'-0" x 10'-0" <input type="checkbox"/> Existing slab/pavement >10'-0" x 10'-0" <input type="checkbox"/> Existing pier and beam	
Existing Building Removal <input type="checkbox"/> Existing structure <10'-0" x 10'-0" <input type="checkbox"/> Existing structure >10'-0" x 10'-0" <input type="checkbox"/> Existing pier and beam	
Septic Tanks <input type="checkbox"/> Septic tanks visually identified <input checked="" type="checkbox"/> No visual evidence of septic tank	
Wells <input type="checkbox"/> Well visually identified <input checked="" type="checkbox"/> No visual evidence of well	
Vegetation, Trash or Debris Removal <input type="checkbox"/> Planting and debris <10 cubic yards <input checked="" type="checkbox"/> Planting and debris > 10 cubic yards	
Existing Fences on Site <input checked="" type="checkbox"/> Chain Link Fence <input type="checkbox"/> Wood Fence <input type="checkbox"/> Wrought Iron/Metal Fence	
Power Poles - Front of Lot/Back of Lot <input checked="" type="checkbox"/> Power pole located at front of lot <input type="checkbox"/> Power pole located in ROW at back of lot <input type="checkbox"/> No power pole visible on lot	
Drainage <input checked="" type="checkbox"/> Lot visibly slopes from back to front <input type="checkbox"/> Lot visibly slopes from front to back <input type="checkbox"/> Can't tell/Unable to visually determine slope	

**Land Assemblage Redevelopment Authority RFP
Attachment L
Lot Inspections**

Area	HCAD	COH Tract #:	Survey Date:
Fifth Ward	0170680000011	2665	May 17, 2006

Address No.	Prefix	Street Name	St. Type	Suffix
2319		LEFFINGWELL	ST	

Curb Cut

Lot A (left) Existing Curb Cut No existing curb cut

Lot B (If applicable-right) Existing curb cut No existing curb cut
 Parcel is only one lot

Lot C (If applicable-furthest right) Existing curb cut No existing curb cut
 Parcel is only one lot

Street Edge (Prevailing on Street) Sidewalks Ditch and Culverts

Trees Located in Right-of-Way No trees observed in ROW Less than 3 trees
 Greater than 3 trees

Trees (>8" Caliper located on Site) No trees Less than 3 trees
 Greater than 3 trees

Existing Slab or Paving Removal Existing slab/pavement <10'-0" x 10'-0"
 Existing slab/pavement >10'-0" x 10'-0" Existing pier and beam

Existing Building Removal Existing structure <10'-0" x 10'-0"
 Existing structure >10'-0" x 10'-0" Existing pier and beam

Septic Tanks Septic tanks visually identified No visual evidence of septic tank

Wells Well visually identified No visual evidence of well

Vegetation, Trash or Debris Removal Planting and debris <10 cubic yards
 Planting and debris > 10 cubic yards

Existing Fences on Site Chain Link Fence Wood Fence
 Wrought Iron/Metal Fence

Power Poles - Front of Lot/Back of Lot Power pole located at front of lot
 Power pole located in ROW at back of lot No power pole visible on lot

Drainage Lot visibly slopes from back to front
 Lot visibly slopes from front to back Can't tell/Unable to visually determine slope

**Land Assemblage Redevelopment Authority RFP
Attachment L
Lot Inspections**

Area	HCAD	COH Tract #:	Survey Date:
Fifth Ward	0170680000012	2672	May 17, 2006

Address No.	Prefix	Street Name	St. Type	Suffix
2323		LEFFINGWELL	ST	

Curb Cut

Lot A (left) Existing Curb Cut No existing curb cut

Lot B (If applicable-right) Existing curb cut No existing curb cut
 Parcel is only one lot

Lot C (If applicable-furthest right) Existing curb cut No existing curb cut
 Parcel is only one lot

Street Edge (Prevailing on Street) Sidewalks Ditch and Culverts

Trees Located in Right-of-Way No trees observed in ROW Less than 3 trees
 Greater than 3 trees

Trees (>8" Caliper located on Site) No trees Less than 3 trees
 Greater than 3 trees

Existing Slab or Paving Removal Existing slab/pavement <10'-0" x 10'-0"
 Existing slab/pavement >10'-0" x 10'-0" Existing pier and beam

Existing Building Removal Existing structure <10'-0" x 10'-0"
 Existing structure >10'-0" x 10'-0" Existing pier and beam

Septic Tanks Septic tanks visually identified No visual evidence of septic tank

Wells Well visually identified No visual evidence of well

Vegetation, Trash or Debris Removal Planting and debris <10 cubic yards
 Planting and debris > 10 cubic yards

Existing Fences on Site Chain Link Fence Wood Fence
 Wrought Iron/Metal Fence

Power Poles - Front of Lot/Back of Lot Power pole located at front of lot
 Power pole located in ROW at back of lot No power pole visible on lot

Drainage Lot visibly slopes from back to front
 Lot visibly slopes from front to back Can't tell/Unable to visually determine slope

**Land Assemblage Redevelopment Authority RFP
Attachment L
Lot Inspections**

Area	HCAD	COH Tract #:	Survey Date:
Fifth Ward	0561440000010	5518	May 17, 2006

Address No.	Prefix	Street Name	St. Type	Suffix
4037		LELIA	ST	

Curb Cut

Lot A (left) Existing Curb Cut No existing curb cut

Lot B (If applicable-right) Existing curb cut No existing curb cut
 Parcel is only one lot

Lot C (If applicable-furthest right) Existing curb cut No existing curb cut
 Parcel is only one lot

Street Edge (Prevailing on Street) Sidewalks Ditch and Culverts

Trees Located in Right-of-Way No trees observed in ROW Less than 3 trees
 Greater than 3 trees

Trees (>8" Caliper located on Site) No trees Less than 3 trees
 Greater than 3 trees

Existing Slab or Paving Removal Existing slab/pavement <10'-0" x 10'-0"
 Existing slab/pavement >10'-0" x 10'-0" Existing pier and beam

Existing Building Removal Existing structure <10'-0" x 10'-0"
 Existing structure >10'-0" x 10'-0" Existing pier and beam

Septic Tanks Septic tanks visually identified No visual evidence of septic tank

Wells Well visually identified No visual evidence of well

Vegetation, Trash or Debris Removal Planting and debris <10 cubic yards
 Planting and debris > 10 cubic yards

Existing Fences on Site Chain Link Fence Wood Fence
 Wrought Iron/Metal Fence

Power Poles - Front of Lot/Back of Lot Power pole located at front of lot
 Power pole located in ROW at back of lot No power pole visible on lot

Drainage Lot visibly slopes from back to front
 Lot visibly slopes from front to back Can't tell/Unable to visually determine slope

**Land Assemblage Redevelopment Authority RFP
Attachment L
Lot Inspections**

Area	HCAD	COH Tract #:	Survey Date:
Fifth Ward	0300190010005	2658	May 17, 2006

Address No.	Prefix	Street Name	St. Type	Suffix
0		LUCILLE		

Curb Cut	
Lot A (left)	<input type="checkbox"/> Existing Curb Cut <input type="checkbox"/> No existing curb cut
Lot B (If applicable-right)	<input type="checkbox"/> Existing curb cut <input type="checkbox"/> No existing curb cut <input type="checkbox"/> Parcel is only one lot
Lot C (If applicable-furthest right)	<input type="checkbox"/> Existing curb cut <input type="checkbox"/> No existing curb cut <input type="checkbox"/> Parcel is only one lot
Street Edge (Prevailing on Street) <input type="checkbox"/> Sidewalks <input checked="" type="checkbox"/> Ditch and Culverts	
Trees Located in Right-of-Way <input type="checkbox"/> No trees observed in ROW <input type="checkbox"/> Less than 3 trees <input type="checkbox"/> Greater than 3 trees	
Trees (>8" Caliper located on Site) <input type="checkbox"/> No trees <input type="checkbox"/> Less than 3 trees <input checked="" type="checkbox"/> Greater than 3 trees	
Existing Slab or Paving Removal <input type="checkbox"/> Existing slab/pavement <10'-0" x 10'-0" <input type="checkbox"/> Existing slab/pavement >10'-0" x 10'-0" <input type="checkbox"/> Existing pier and beam	
Existing Building Removal <input type="checkbox"/> Existing structure <10'-0" x 10'-0" <input type="checkbox"/> Existing structure >10'-0" x 10'-0" <input type="checkbox"/> Existing pier and beam	
Septic Tanks <input type="checkbox"/> Septic tanks visually identified <input checked="" type="checkbox"/> No visual evidence of septic tank	
Wells <input type="checkbox"/> Well visually identified <input checked="" type="checkbox"/> No visual evidence of well	
Vegetation, Trash or Debris Removal <input type="checkbox"/> Planting and debris <10 cubic yards <input checked="" type="checkbox"/> Planting and debris > 10 cubic yards	
Existing Fences on Site <input checked="" type="checkbox"/> Chain Link Fence <input type="checkbox"/> Wood Fence <input type="checkbox"/> Wrought Iron/Metal Fence	
Power Poles - Front of Lot/Back of Lot <input checked="" type="checkbox"/> Power pole located at front of lot <input type="checkbox"/> Power pole located in ROW at back of lot <input type="checkbox"/> No power pole visible on lot	
Drainage <input checked="" type="checkbox"/> Lot visibly slopes from back to front <input type="checkbox"/> Lot visibly slopes from front to back <input type="checkbox"/> Can't tell/Unable to visually determine slope	

**Land Assemblage Redevelopment Authority RFP
Attachment L
Lot Inspections**

Area	HCAD	COH Tract #:	Survey Date:
Fifth Ward	0402660090062	2591	May 17, 2006

Address No.	Prefix	Street Name	St. Type	Suffix
0		LUCILLE		

Curb Cut

Lot A (left) Existing Curb Cut No existing curb cut

Lot B (If applicable-right) Existing curb cut No existing curb cut
 Parcel is only one lot

Lot C (If applicable-furthest right) Existing curb cut No existing curb cut
 Parcel is only one lot

Street Edge (Prevailing on Street) Sidewalks Ditch and Culverts

Trees Located in Right-of-Way No trees observed in ROW Less than 3 trees
 Greater than 3 trees

Trees (>8" Caliper located on Site) No trees Less than 3 trees
 Greater than 3 trees

Existing Slab or Paving Removal Existing slab/pavement <10'-0" x 10'-0"
 Existing slab/pavement >10'-0" x 10'-0" Existing pier and beam

Existing Building Removal Existing structure <10'-0" x 10'-0"
 Existing structure >10'-0" x 10'-0" Existing pier and beam

Septic Tanks Septic tanks visually identified No visual evidence of septic tank

Wells Well visually identified No visual evidence of well

Vegetation, Trash or Debris Removal Planting and debris <10 cubic yards
 Planting and debris > 10 cubic yards

Existing Fences on Site Chain Link Fence Wood Fence
 Wrought Iron/Metal Fence

Power Poles - Front of Lot/Back of Lot Power pole located at front of lot
 Power pole located in ROW at back of lot No power pole visible on lot

Drainage Lot visibly slopes from back to front
 Lot visibly slopes from front to back Can't tell/Unable to visually determine slope

**Land Assemblage Redevelopment Authority RFP
Attachment L
Lot Inspections**

Area	HCAD	COH Tract #:	Survey Date:
Fifth Ward	0561440000019	2661	May 19, 2006

Address No.	Prefix	Street Name	St. Type	Suffix
0		LUCILLE		

Curb Cut				
Lot A (left) <input type="checkbox"/> Existing Curb Cut <input type="checkbox"/> No existing curb cut				
Lot B (If applicable-right) <input type="checkbox"/> Existing curb cut <input type="checkbox"/> No existing curb cut <input type="checkbox"/> Parcel is only one lot				
Lot C (If applicable-furthest right) <input type="checkbox"/> Existing curb cut <input type="checkbox"/> No existing curb cut <input type="checkbox"/> Parcel is only one lot				
Street Edge (Prevailing on Street) <input type="checkbox"/> Sidewalks <input checked="" type="checkbox"/> Ditch and Culverts				
Trees Located in Right-of-Way <input type="checkbox"/> No trees observed in ROW <input type="checkbox"/> Less than 3 trees <input type="checkbox"/> Greater than 3 trees				
Trees (>8" Caliper located on Site) <input type="checkbox"/> No trees <input type="checkbox"/> Less than 3 trees <input checked="" type="checkbox"/> Greater than 3 trees				
Existing Slab or Paving Removal <input type="checkbox"/> Existing slab/pavement <10'-0" x 10'-0" <input type="checkbox"/> Existing slab/pavement >10'-0" x 10'-0" <input type="checkbox"/> Existing pier and beam				
Existing Building Removal <input type="checkbox"/> Existing structure <10'-0" x 10'-0" <input type="checkbox"/> Existing structure >10'-0" x 10'-0" <input type="checkbox"/> Existing pier and beam				
Septic Tanks <input type="checkbox"/> Septic tanks visually identified <input checked="" type="checkbox"/> No visual evidence of septic tank				
Wells <input type="checkbox"/> Well visually identified <input checked="" type="checkbox"/> No visual evidence of well				
Vegetation, Trash or Debris Removal <input checked="" type="checkbox"/> Planting and debris <10 cubic yards <input type="checkbox"/> Planting and debris > 10 cubic yards				
Existing Fences on Site <input checked="" type="checkbox"/> Chain Link Fence <input type="checkbox"/> Wood Fence <input type="checkbox"/> Wrought Iron/Metal Fence				
Power Poles - Front of Lot/Back of Lot <input checked="" type="checkbox"/> Power pole located at front of lot <input type="checkbox"/> Power pole located in ROW at back of lot <input type="checkbox"/> No power pole visible on lot				
Drainage <input checked="" type="checkbox"/> Lot visibly slopes from back to front <input type="checkbox"/> Lot visibly slopes from front to back <input type="checkbox"/> Can't tell/Unable to visually determine slope				

**Land Assemblage Redevelopment Authority RFP
Attachment L
Lot Inspections**

Area	HCAD	COH Tract #:	Survey Date:
Fifth Ward	0300190010002	2660	May 17, 2006

Address No.	Prefix	Street Name	St. Type	Suffix
3706		LUCILLE	ST	

Curb Cut

Lot A (left) Existing Curb Cut No existing curb cut

Lot B (If applicable-right) Existing curb cut No existing curb cut
 Parcel is only one lot

Lot C (If applicable-furthest right) Existing curb cut No existing curb cut
 Parcel is only one lot

Street Edge (Prevailing on Street) Sidewalks Ditch and Culverts

Trees Located in Right-of-Way No trees observed in ROW Less than 3 trees
 Greater than 3 trees

Trees (>8" Caliper located on Site) No trees Less than 3 trees
 Greater than 3 trees

Existing Slab or Paving Removal Existing slab/pavement <10'-0" x 10'-0"
 Existing slab/pavement >10'-0" x 10'-0" Existing pier and beam

Existing Building Removal Existing structure <10'-0" x 10'-0"
 Existing structure >10'-0" x 10'-0" Existing pier and beam

Septic Tanks Septic tanks visually identified No visual evidence of septic tank

Wells Well visually identified No visual evidence of well

Vegetation, Trash or Debris Removal Planting and debris <10 cubic yards
 Planting and debris > 10 cubic yards

Existing Fences on Site Chain Link Fence Wood Fence
 Wrought Iron/Metal Fence

Power Poles - Front of Lot/Back of Lot Power pole located at front of lot
 Power pole located in ROW at back of lot No power pole visible on lot

Drainage Lot visibly slopes from back to front
 Lot visibly slopes from front to back Can't tell/Unable to visually determine slope

**Land Assemblage Redevelopment Authority RFP
Attachment L
Lot Inspections**

Area	HCAD	COH Tract #:	Survey Date:
Fifth Ward	0300190010003	2659	May 17, 2006

Address No.	Prefix	Street Name	St. Type	Suffix
3710		LUCILLE	ST	

Curb Cut

Lot A (left) Existing Curb Cut No existing curb cut

Lot B (If applicable-right) Existing curb cut No existing curb cut
 Parcel is only one lot

Lot C (If applicable-furthest right) Existing curb cut No existing curb cut
 Parcel is only one lot

Street Edge (Prevailing on Street) Sidewalks Ditch and Culverts

Trees Located in Right-of-Way No trees observed in ROW Less than 3 trees
 Greater than 3 trees

Trees (>8" Caliper located on Site) No trees Less than 3 trees
 Greater than 3 trees

Existing Slab or Paving Removal Existing slab/pavement <10'-0" x 10'-0"
 Existing slab/pavement >10'-0" x 10'-0" Existing pier and beam

Existing Building Removal Existing structure <10'-0" x 10'-0"
 Existing structure >10'-0" x 10'-0" Existing pier and beam

Septic Tanks Septic tanks visually identified No visual evidence of septic tank

Wells Well visually identified No visual evidence of well

Vegetation, Trash or Debris Removal Planting and debris <10 cubic yards
 Planting and debris > 10 cubic yards

Existing Fences on Site Chain Link Fence Wood Fence
 Wrought Iron/Metal Fence

Power Poles - Front of Lot/Back of Lot Power pole located at front of lot
 Power pole located in ROW at back of lot No power pole visible on lot

Drainage Lot visibly slopes from back to front
 Lot visibly slopes from front to back Can't tell/Unable to visually determine slope

**Land Assemblage Redevelopment Authority RFP
Attachment L
Lot Inspections**

Area	HCAD	COH Tract #:	Survey Date:
Fifth Ward	0701040010002	2576	May 17, 2006

Address No.	Prefix	Street Name	St. Type	Suffix
4009		LUCILLE		

Curb Cut

Lot A (left) Existing Curb Cut No existing curb cut

Lot B (If applicable-right) Existing curb cut No existing curb cut
 Parcel is only one lot

Lot C (If applicable-furthest right) Existing curb cut No existing curb cut
 Parcel is only one lot

Street Edge (Prevailing on Street) Sidewalks Ditch and Culverts

Trees Located in Right-of-Way No trees observed in ROW Less than 3 trees
 Greater than 3 trees

Trees (>8" Caliper located on Site) No trees Less than 3 trees
 Greater than 3 trees

Existing Slab or Paving Removal Existing slab/pavement <10'-0" x 10'-0"
 Existing slab/pavement >10'-0" x 10'-0" Existing pier and beam

Existing Building Removal Existing structure <10'-0" x 10'-0"
 Existing structure >10'-0" x 10'-0" Existing pier and beam

Septic Tanks Septic tanks visually identified No visual evidence of septic tank

Wells Well visually identified No visual evidence of well

Vegetation, Trash or Debris Removal Planting and debris <10 cubic yards
 Planting and debris > 10 cubic yards

Existing Fences on Site Chain Link Fence Wood Fence
 Wrought Iron/Metal Fence

Power Poles - Front of Lot/Back of Lot Power pole located at front of lot
 Power pole located in ROW at back of lot No power pole visible on lot

Drainage Lot visibly slopes from back to front
 Lot visibly slopes from front to back Can't tell/Unable to visually determine slope

**Land Assemblage Redevelopment Authority RFP
Attachment L
Lot Inspections**

Area	HCAD	COH Tract #:	Survey Date:
Fifth Ward	0701040020003	2573	May 17, 2006

Address No.	Prefix	Street Name	St. Type	Suffix
4012		LUCILLE		

Curb Cut
Lot A (left) Existing Curb Cut No existing curb cut
Lot B (If applicable-right) Existing curb cut No existing curb cut
 Parcel is only one lot
Lot C (If applicable-furthest right) Existing curb cut No existing curb cut
 Parcel is only one lot

Street Edge (Prevailing on Street) Sidewalks Ditch and Culverts

Trees Located in Right-of-Way No trees observed in ROW Less than 3 trees
 Greater than 3 trees

Trees (>8" Caliper located on Site) No trees Less than 3 trees
 Greater than 3 trees

Existing Slab or Paving Removal Existing slab/pavement <10'-0" x 10'-0"
 Existing slab/pavement >10'-0" x 10'-0" Existing pier and beam

Existing Building Removal Existing structure <10'-0" x 10'-0"
 Existing structure >10'-0" x 10'-0" Existing pier and beam

Septic Tanks Septic tanks visually identified No visual evidence of septic tank

Wells Well visually identified No visual evidence of well

Vegetation, Trash or Debris Removal Planting and debris <10 cubic yards
 Planting and debris > 10 cubic yards

Existing Fences on Site Chain Link Fence Wood Fence
 Wrought Iron/Metal Fence

Power Poles - Front of Lot/Back of Lot Power pole located at front of lot
 Power pole located in ROW at back of lot No power pole visible on lot

Drainage Lot visibly slopes from back to front
 Lot visibly slopes from front to back Can't tell/Unable to visually determine slope

**Land Assemblage Redevelopment Authority RFP
Attachment L
Lot Inspections**

Area	HCAD	COH Tract #:	Survey Date:
Fifth Ward	0151990000010	2668	May 17, 2006

Address No.	Prefix	Street Name	St. Type	Suffix
0		NOBLE		

Curb Cut				
Lot A (left) <input type="checkbox"/> Existing Curb Cut <input type="checkbox"/> No existing curb cut				
Lot B (If applicable-right) <input type="checkbox"/> Existing curb cut <input type="checkbox"/> No existing curb cut <input type="checkbox"/> Parcel is only one lot				
Lot C (If applicable-furthest right) <input type="checkbox"/> Existing curb cut <input type="checkbox"/> No existing curb cut <input type="checkbox"/> Parcel is only one lot				
Street Edge (Prevailing on Street) <input checked="" type="checkbox"/> Sidewalks <input type="checkbox"/> Ditch and Culverts				
Trees Located in Right-of-Way <input type="checkbox"/> No trees observed in ROW <input type="checkbox"/> Less than 3 trees <input type="checkbox"/> Greater than 3 trees				
Trees (>8" Caliper located on Site) <input type="checkbox"/> No trees <input type="checkbox"/> Less than 3 trees <input checked="" type="checkbox"/> Greater than 3 trees				
Existing Slab or Paving Removal <input type="checkbox"/> Existing slab/pavement <10'-0" x 10'-0" <input type="checkbox"/> Existing slab/pavement >10'-0" x 10'-0" <input type="checkbox"/> Existing pier and beam				
Existing Building Removal <input type="checkbox"/> Existing structure <10'-0" x 10'-0" <input type="checkbox"/> Existing structure >10'-0" x 10'-0" <input type="checkbox"/> Existing pier and beam				
Septic Tanks <input type="checkbox"/> Septic tanks visually identified <input checked="" type="checkbox"/> No visual evidence of septic tank				
Wells <input type="checkbox"/> Well visually identified <input checked="" type="checkbox"/> No visual evidence of well				
Vegetation, Trash or Debris Removal <input type="checkbox"/> Planting and debris <10 cubic yards <input type="checkbox"/> Planting and debris > 10 cubic yards				
Existing Fences on Site <input checked="" type="checkbox"/> Chain Link Fence <input type="checkbox"/> Wood Fence <input type="checkbox"/> Wrought Iron/Metal Fence				
Power Poles - Front of Lot/Back of Lot <input checked="" type="checkbox"/> Power pole located at front of lot <input type="checkbox"/> Power pole located in ROW at back of lot <input type="checkbox"/> No power pole visible on lot				
Drainage <input checked="" type="checkbox"/> Lot visibly slopes from back to front <input type="checkbox"/> Lot visibly slopes from front to back <input type="checkbox"/> Can't tell/Unable to visually determine slope				

Land Assemblage Redevelopment Authority RFP

Attachment L

Lot Inspections

Area	HCAD	COH Tract #:	Survey Date:
Fifth Ward	0561330000010	2579	May 17, 2006

Address No.	Prefix	Street Name	St. Type	Suffix
2610		RUSSELL		

Curb Cut

Lot A (left) Existing Curb Cut No existing curb cut

Lot B (If applicable-right) Existing curb cut No existing curb cut
 Parcel is only one lot

Lot C (If applicable-furthest right) Existing curb cut No existing curb cut
 Parcel is only one lot

Street Edge (Prevailing on Street) Sidewalks Ditch and Culverts

Trees Located in Right-of-Way No trees observed in ROW Less than 3 trees
 Greater than 3 trees

Trees (>8" Caliper located on Site) No trees Less than 3 trees
 Greater than 3 trees

Existing Slab or Paving Removal Existing slab/pavement <10'-0" x 10'-0"
 Existing slab/pavement >10'-0" x 10'-0" Existing pier and beam

Existing Building Removal Existing structure <10'-0" x 10'-0"
 Existing structure >10'-0" x 10'-0" Existing pier and beam

Septic Tanks Septic tanks visually identified No visual evidence of septic tank

Wells Well visually identified No visual evidence of well

Vegetation, Trash or Debris Removal Planting and debris <10 cubic yards
 Planting and debris > 10 cubic yards

Existing Fences on Site Chain Link Fence Wood Fence
 Wrought Iron/Metal Fence

Power Poles - Front of Lot/Back of Lot Power pole located at front of lot
 Power pole located in ROW at back of lot No power pole visible on lot

Drainage Lot visibly slopes from back to front
 Lot visibly slopes from front to back Can't tell/Unable to visually determine slope

**Land Assemblage Redevelopment Authority RFP
Attachment L
Lot Inspections**

Area	HCAD	COH Tract #:	Survey Date:
Fifth Ward	0092410000002	2662	May 18, 2006

Address No.	Prefix	Street Name	St. Type	Suffix
0		SAKOWITZ	DR	

Curb Cut

Lot A (left) Existing Curb Cut No existing curb cut

Lot B (If applicable-right) Existing curb cut No existing curb cut
 Parcel is only one lot

Lot C (If applicable-furthest right) Existing curb cut No existing curb cut
 Parcel is only one lot

Street Edge (Prevailing on Street) Sidewalks Ditch and Culverts

Trees Located in Right-of-Way No trees observed in ROW Less than 3 trees
 Greater than 3 trees

Trees (>8" Caliper located on Site) No trees Less than 3 trees
 Greater than 3 trees

Existing Slab or Paving Removal Existing slab/pavement <10'-0" x 10'-0"
 Existing slab/pavement >10'-0" x 10'-0" Existing pier and beam

Existing Building Removal Existing structure <10'-0" x 10'-0"
 Existing structure >10'-0" x 10'-0" Existing pier and beam

Septic Tanks Septic tanks visually identified No visual evidence of septic tank

Wells Well visually identified No visual evidence of well

Vegetation, Trash or Debris Removal Planting and debris <10 cubic yards
 Planting and debris > 10 cubic yards

Existing Fences on Site Chain Link Fence Wood Fence
 Wrought Iron/Metal Fence

Power Poles - Front of Lot/Back of Lot Power pole located at front of lot
 Power pole located in ROW at back of lot No power pole visible on lot

Drainage Lot visibly slopes from back to front
 Lot visibly slopes from front to back Can't tell/Unable to visually determine slope

**Land Assemblage Redevelopment Authority RFP
Attachment L
Lot Inspections**

Area	HCAD	COH Tract #:	Survey Date:
Fifth Ward	0092470000001	5521	May 18, 2006

Address No.	Prefix	Street Name	St. Type	Suffix
0		SAKOWITZ		

Curb Cut
Lot A (left) Existing Curb Cut No existing curb cut
Lot B (If applicable-right) Existing curb cut No existing curb cut
 Parcel is only one lot
Lot C (If applicable-furthest right) Existing curb cut No existing curb cut
 Parcel is only one lot

Street Edge (Prevailing on Street) Sidewalks Ditch and Culverts

Trees Located in Right-of-Way No trees observed in ROW Less than 3 trees
 Greater than 3 trees

Trees (>8" Caliper located on Site) No trees Less than 3 trees
 Greater than 3 trees

Existing Slab or Paving Removal Existing slab/pavement <10'-0" x 10'-0"
 Existing slab/pavement >10'-0" x 10'-0" Existing pier and beam

Existing Building Removal Existing structure <10'-0" x 10'-0"
 Existing structure >10'-0" x 10'-0" Existing pier and beam

Septic Tanks Septic tanks visually identified No visual evidence of septic tank

Wells Well visually identified No visual evidence of well

Vegetation, Trash or Debris Removal Planting and debris <10 cubic yards
 Planting and debris > 10 cubic yards

Existing Fences on Site Chain Link Fence Wood Fence
 Wrought Iron/Metal Fence

Power Poles - Front of Lot/Back of Lot Power pole located at front of lot
 Power pole located in ROW at back of lot No power pole visible on lot

Drainage Lot visibly slopes from back to front
 Lot visibly slopes from front to back Can't tell/Unable to visually determine slope

**Land Assemblage Redevelopment Authority RFP
Attachment L
Lot Inspections**

Area	HCAD	COH Tract #:	Survey Date:
Fifth Ward	0092350000002	2585	May 18, 2006

Address No.	Prefix	Street Name	St. Type	Suffix
2111		SAKOWITZ		

Curb Cut

Lot A (left) Existing Curb Cut No existing curb cut

Lot B (If applicable-right) Existing curb cut No existing curb cut
 Parcel is only one lot

Lot C (If applicable-furthest right) Existing curb cut No existing curb cut
 Parcel is only one lot

Street Edge (Prevailing on Street) Sidewalks Ditch and Culverts

Trees Located in Right-of-Way No trees observed in ROW Less than 3 trees
 Greater than 3 trees

Trees (>8" Caliper located on Site) No trees Less than 3 trees
 Greater than 3 trees

Existing Slab or Paving Removal Existing slab/pavement <10'-0" x 10'-0"
 Existing slab/pavement >10'-0" x 10'-0" Existing pier and beam

Existing Building Removal Existing structure <10'-0" x 10'-0"
 Existing structure >10'-0" x 10'-0" Existing pier and beam

Septic Tanks Septic tanks visually identified No visual evidence of septic tank

Wells Well visually identified No visual evidence of well

Vegetation, Trash or Debris Removal Planting and debris <10 cubic yards
 Planting and debris > 10 cubic yards

Existing Fences on Site Chain Link Fence Wood Fence
 Wrought Iron/Metal Fence

Power Poles - Front of Lot/Back of Lot Power pole located at front of lot
 Power pole located in ROW at back of lot No power pole visible on lot

Drainage Lot visibly slopes from back to front
 Lot visibly slopes from front to back Can't tell/Unable to visually determine slope

**Land Assemblage Redevelopment Authority RFP
Attachment L
Lot Inspections**

Area	HCAD	COH Tract #:	Survey Date:
Fifth Ward	0092350000010	5520	May 17, 2006

Address No.	Prefix	Street Name	St. Type	Suffix
2110		SAM WILSON	ST	

Curb Cut

Lot A (left) Existing Curb Cut No existing curb cut

Lot B (If applicable-right) Existing curb cut No existing curb cut
 Parcel is only one lot

Lot C (If applicable-furthest right) Existing curb cut No existing curb cut
 Parcel is only one lot

Street Edge (Prevailing on Street) Sidewalks Ditch and Culverts

Trees Located in Right-of-Way No trees observed in ROW Less than 3 trees
 Greater than 3 trees

Trees (>8" Caliper located on Site) No trees Less than 3 trees
 Greater than 3 trees

Existing Slab or Paving Removal Existing slab/pavement <10'-0" x 10'-0"
 Existing slab/pavement >10'-0" x 10'-0" Existing pier and beam

Existing Building Removal Existing structure <10'-0" x 10'-0"
 Existing structure >10'-0" x 10'-0" Existing pier and beam

Septic Tanks Septic tanks visually identified No visual evidence of septic tank

Wells Well visually identified No visual evidence of well

Vegetation, Trash or Debris Removal Planting and debris <10 cubic yards
 Planting and debris > 10 cubic yards

Existing Fences on Site Chain Link Fence Wood Fence
 Wrought Iron/Metal Fence

Power Poles - Front of Lot/Back of Lot Power pole located at front of lot
 Power pole located in ROW at back of lot No power pole visible on lot

Drainage Lot visibly slopes from back to front
 Lot visibly slopes from front to back Can't tell/Unable to visually determine slope

**Land Assemblage Redevelopment Authority RFP
Attachment L
Lot Inspections**

Area	HCAD	COH Tract #:	Survey Date:
Fifth Ward	0092410000006	2584	May 17, 2006

Address No.	Prefix	Street Name	St. Type	Suffix
2208		SAM WILSON		

Curb Cut

Lot A (left) Existing Curb Cut No existing curb cut

Lot B (If applicable-right) Existing curb cut No existing curb cut
 Parcel is only one lot

Lot C (If applicable-furthest right) Existing curb cut No existing curb cut
 Parcel is only one lot

Street Edge (Prevailing on Street) Sidewalks Ditch and Culverts

Trees Located in Right-of-Way No trees observed in ROW Less than 3 trees
 Greater than 3 trees

Trees (>8" Caliper located on Site) No trees Less than 3 trees
 Greater than 3 trees

Existing Slab or Paving Removal Existing slab/pavement <10'-0" x 10'-0"
 Existing slab/pavement >10'-0" x 10'-0" Existing pier and beam

Existing Building Removal Existing structure <10'-0" x 10'-0"
 Existing structure >10'-0" x 10'-0" Existing pier and beam

Septic Tanks Septic tanks visually identified No visual evidence of septic tank

Wells Well visually identified No visual evidence of well

Vegetation, Trash or Debris Removal Planting and debris <10 cubic yards
 Planting and debris > 10 cubic yards

Existing Fences on Site Chain Link Fence Wood Fence
 Wrought Iron/Metal Fence

Power Poles - Front of Lot/Back of Lot Power pole located at front of lot
 Power pole located in ROW at back of lot No power pole visible on lot

Drainage Lot visibly slopes from back to front
 Lot visibly slopes from front to back Can't tell/Unable to visually determine slope

**Land Assemblage Redevelopment Authority RFP
Attachment L
Lot Inspections**

Area	HCAD	COH Tract #:	Survey Date:
Fifth Ward	0092480000006	2583	May 17, 2006

Address No.	Prefix	Street Name	St. Type	Suffix
2422		SAM WILSON		

Curb Cut

Lot A (left) Existing Curb Cut No existing curb cut

Lot B (If applicable-right) Existing curb cut No existing curb cut
 Parcel is only one lot

Lot C (If applicable-furthest right) Existing curb cut No existing curb cut
 Parcel is only one lot

Street Edge (Prevailing on Street) Sidewalks Ditch and Culverts

Trees Located in Right-of-Way No trees observed in ROW Less than 3 trees
 Greater than 3 trees

Trees (>8" Caliper located on Site) No trees Less than 3 trees
 Greater than 3 trees

Existing Slab or Paving Removal Existing slab/pavement <10'-0" x 10'-0"
 Existing slab/pavement >10'-0" x 10'-0" Existing pier and beam

Existing Building Removal Existing structure <10'-0" x 10'-0"
 Existing structure >10'-0" x 10'-0" Existing pier and beam

Septic Tanks Septic tanks visually identified No visual evidence of septic tank

Wells Well visually identified No visual evidence of well

Vegetation, Trash or Debris Removal Planting and debris <10 cubic yards
 Planting and debris > 10 cubic yards

Existing Fences on Site Chain Link Fence Wood Fence
 Wrought Iron/Metal Fence

Power Poles - Front of Lot/Back of Lot Power pole located at front of lot
 Power pole located in ROW at back of lot No power pole visible on lot

Drainage Lot visibly slopes from back to front
 Lot visibly slopes from front to back Can't tell/Unable to visually determine slope

**Land Assemblage Redevelopment Authority RFP
Attachment L
Lot Inspections**

Area	HCAD	COH Tract #:	Survey Date:
Fifth Ward	0151990000009	2669	May 17, 2006

Address No.	Prefix	Street Name	St. Type	Suffix
2017		WEST	ST	

Curb Cut

Lot A (left) Existing Curb Cut No existing curb cut

Lot B (If applicable-right) Existing curb cut No existing curb cut
 Parcel is only one lot

Lot C (If applicable-furthest right) Existing curb cut No existing curb cut
 Parcel is only one lot

Street Edge (Prevailing on Street) Sidewalks Ditch and Culverts

Trees Located in Right-of-Way No trees observed in ROW Less than 3 trees
 Greater than 3 trees

Trees (>8" Caliper located on Site) No trees Less than 3 trees
 Greater than 3 trees

Existing Slab or Paving Removal Existing slab/pavement <10'-0" x 10'-0"
 Existing slab/pavement >10'-0" x 10'-0" Existing pier and beam

Existing Building Removal Existing structure <10'-0" x 10'-0"
 Existing structure >10'-0" x 10'-0" Existing pier and beam

Septic Tanks Septic tanks visually identified No visual evidence of septic tank

Wells Well visually identified No visual evidence of well

Vegetation, Trash or Debris Removal Planting and debris <10 cubic yards
 Planting and debris > 10 cubic yards

Existing Fences on Site Chain Link Fence Wood Fence
 Wrought Iron/Metal Fence

Power Poles - Front of Lot/Back of Lot Power pole located at front of lot
 Power pole located in ROW at back of lot No power pole visible on lot

Drainage Lot visibly slopes from back to front
 Lot visibly slopes from front to back Can't tell/Unable to visually determine slope

**Land Assemblage Redevelopment Authority RFP
Attachment L
Lot Inspections**

Area	HCAD	COH Tract #:	Survey Date:
Fifth Ward	0300200040011	5565	May 17, 2006

Address No.	Prefix	Street Name	St. Type	Suffix
3703		WYLIE		

Curb Cut

Lot A (left) Existing Curb Cut No existing curb cut

Lot B (If applicable-right) Existing curb cut No existing curb cut
 Parcel is only one lot

Lot C (If applicable-furthest right) Existing curb cut No existing curb cut
 Parcel is only one lot

Street Edge (Prevailing on Street) Sidewalks Ditch and Culverts

Trees Located in Right-of-Way No trees observed in ROW Less than 3 trees
 Greater than 3 trees

Trees (>8" Caliper located on Site) No trees Less than 3 trees
 Greater than 3 trees

Existing Slab or Paving Removal Existing slab/pavement <10'-0" x 10'-0"
 Existing slab/pavement >10'-0" x 10'-0" Existing pier and beam

Existing Building Removal Existing structure <10'-0" x 10'-0"
 Existing structure >10'-0" x 10'-0" Existing pier and beam

Septic Tanks Septic tanks visually identified No visual evidence of septic tank

Wells Well visually identified No visual evidence of well

Vegetation, Trash or Debris Removal Planting and debris <10 cubic yards
 Planting and debris > 10 cubic yards

Existing Fences on Site Chain Link Fence Wood Fence
 Wrought Iron/Metal Fence

Power Poles - Front of Lot/Back of Lot Power pole located at front of lot
 Power pole located in ROW at back of lot No power pole visible on lot

Drainage Lot visibly slopes from back to front
 Lot visibly slopes from front to back Can't tell/Unable to visually determine slope