Exterior Elevation 2609 Stanford

(North face)

1



1. Current Elevation

2



2. Current Elevation : Unused Door and window concealed by adjacent property, fence, utility and treecover

3



3. Proposed Elevation : Unused Door and window replaced by window in line with three dining room windows and bordered/ clad in wood exterior to match those other fixed windows


Wooden fence blocking view
old wooden steps
HVAC
condenser
porch

6 of 23

8 of 23